What's New?

ELENA

| *List of modifications* | *From:* | 01.400.00.04 / 14/03/2016 |
| | *To:* | 01.400.00.04 / 14/03/2016 |

Module: PM-Aveva PDMS   **Notes:** 1

Note: ELE-266

It has been fixed a bug in the compiling directive "ScomIndex".
During the execution of the Builder, in some cases, a "ScomIndex" already assigned to other components, could have been given to new components, which were not in the previous version.

Patch Situation   01.400.00.04