

What's New?

ELENA

<i>List of modifications</i>	<i>From:</i>	01.400.00.04 / 14/03/2016
	<i>To:</i>	01.400.00.05 / 23/06/2016

Module: General

Notes: 1

Note: ELE-274

In case of components with the same mark in different piping classes, if the "skip_not_found" parameter was set to 1 (exclusion from catalog and piping classes of components without dimensional values compiled), some records with empty dimensional data were nevertheless included in the catalogue XML result file.

This was due to an improper storage of the missing dimensional tables. When for the first mark was identified the absence of the table it was inserted: in this way, for the second mark, the table resulted present in memory.

It was added a cloning dimensional table method, which allows to operate on the data directly without inserting the missing table in memory, but to insert it only at the end of the process.

Patch Situation 01.400.00.05

Module: PM-Aveva PDMS

Notes: 1

Note: ELE-269

Some components were excluded from the catalog because they are subject to Warning, however, they appeared into SPCOM piping classes sheet.

It was inserted a suitable workararound into ELENA, that prevents this anomalous behavior.

Patch Situation 01.400.00.05